

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 027515
OUTSIDE WORK: NO DATE: 12-22-72
FROM: MORLEY BRO.
FIRED AMMO TYPE: - SAGINAW, MICH.
& CONDITION: _____ GUN #: 6241128
PROOF: R.E.P.-K ^{ASSEMBLER 79} INSP.: 73 TEST: 13 CODE: KU=5/71
HEADING: - GRA./CAL.: 25-06
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: EXCESSIVE RADIUS-REAR APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: _____ APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT.025
BURRS ON TRIGGER. TRIGGER TOO CLOSE TO
GUARD ON RIGHT SIDE. THERE ARE INDICATIONS
OF PRIMER PIERCING ON FIRING PIN ASSEMBLY.

COMPLAINT: "WILL FIRE DURING FEEDING OPERATION."

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. TRIGGER BIND MAY HAVE PREVENTED
PROPER RETRACTION.