

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-11218

INITIAL CUSTOMER ORDER NO.

FJR

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

03/28/94

03/29/94

WS 8-69

6265014

700

7MM MAG

SS

ACCESSORIES

L/MAG BOX

L/WOOD

SCOPE BASE

FROM:

SHIP TO:

MULE, C J
941 PRAKWAY PLACE
PEEKSKILL

NY 10566

MULE, C J
941 PRAKWAY PLACE
PEEKSKILLNY
10566

CUST NO: 094999 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Model 8-69 Unable to duplicate customer concern as noted. Trigger functions normal in every respect. Bolt stop release spring has been bent and twisted out of shape. Small rust pits on underside of Receiver. Firing Pin Head rusting inside of shroud. Rust on Sean and connector. Only fault found was that trigger just needs a good cleaning and free lubrication. Exchange trigger assy at service charge only to restore confidence in Rifle. Reason gathering of good will.

ARTS

COMMENTS

Trigger pull measured +1/2 lbs as sent 11/14 .0105 as Recd.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 03537