

May 15, 1989 --

Remington Arms Co.
1007 Market St.
Wilmington, DE 19898

Gentlemen:


I own a Remington 700 BDL rifle, caliber 30-06, serial number A6200118. The rifle was bought new and only occasionally used for target shooting. It is in excellent condition. The mechanism of the rifle has not been tampered with nor adjusted. It is as it was when it left the factory.

A round was chambered and the safety applied. A few minutes later the safety was released and the rifle fired. My hand was not near the trigger.

The round fitted into the chamber freely and was not forced by the bolt.

I repeated the sequence with a dummy round any number of times later but did not experience the same reaction. Your advice is requested.

Sincerely,


JOSEPH J. MURRAY
8922 W. Progress Place
Littleton, CO 80123