

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: FAIR R #: 12986
OUTSIDE WORK: SCOPE MOUNTED DATE: 6-28-71
FROM: NAT. PARK SERV.
FIRED AMMO TYPE: - KAHULUI, MAUI, HAWAII
& CONDITION: _____ GUN #: 6258726
PROOF: R.I.P.-E INSP.: U TEST: 87 CODE: 05 = 7/69
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO COMPONENT BROKEN.

CONNECTOR CLEARANCE ON TRIGGER = 1.070 M/D = $\frac{1.079}{1.070} = 1.008$

TRIGGER CLEARANCE ON CONNECTOR = 1.090 M/D = $\frac{1.083}{1.080} = 1.010$

CONNECTOR-SEAR ENGAGEMENT O.K.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.

COMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.

THE TRIGGER CONNECTOR-TRIGGER NOT TO
MODEL DRAWING, PERMIT SEAR, CONNECTOR
INTERFERENCE - FAILURE TO RETRACT.