

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: FAIR R #: 11954
OUTSIDE WORK: SCOPE MOUNTED DATE: 6-2-71
FROM: NATIONAL PK. SVS.
FIRED AMMO TYPE: - KAHULULU, MAUI, HAWAII
& CONDITION: _____ GUN #: 6258351
PROOF: R.E.P.-E. ASSEMBLER 64 INSP.: U TEST: 87 CODE: 05 = 7/69
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN ETC. COMPONENTS.

CONNECTOR CLEARANCE ON TRIGGER = 1.069 M/D = ^{1.079}1.076 - .007

TRIGGER CLEARANCE ON CONNECTOR = 1.089 M/D = ^{1.083}1.080 + .006

CONNECTOR - SEAR ENGAGEMENT = .015 (.005 UNDER MIN.)

TRIGGER PULL FIVE POUNDS. EXCESSIVE LUBRICANT & DIRTY.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT

COMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.

THE TRIGGER - CONNECTOR & TRIGGER NOT TO MODEL

DRAWING, PERMIT SEAR, CONNECTOR INTERFERENCE,

FAILURE TO RETRACT.