

RECEIVING AND ESTIMATING REPORT

COMMENTS

✓ R ORDER
94-07883

INITIAL CUSTOMER ORDER NO.

TAL

DATE RECEIVED 02/25/94 DATE OPENED 03/04/94 DATE CODE XT 12-70 SERIAL NUMBER 6372464 NEW SERIAL NUMBER MODEL AND GRADE 700 7MM BDL/SS

ACCESSORIES

FROM:

SHIP TO:

NORRIS, EDWARD L.
9371 CR 1141
TYLER

NORRIS, EDWARD L.
9371 CR 1141
TYLER

TX 75709

TX
75709

CUST NO: 093378 B.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE 215.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, the following damage was noted. Bolt trigger assembly
too loose, when safety was engaged it would not move. Trigger group
is loose or from being dropped. When shot trigger assembly slipping with
a heavy jumpy resistance.

PARTS

COMMENTS

CREDIT CARD

Credit Card

5396-8000-1299-9748

395

903-593 6097

Replace complete trigger assembly
or when action is normal
adjustment not to pattern of shot with
go ahead per phone 3/27/94

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94