

RECEIVING AND ESTIMATING REPORT

TIAL		CUSTOMER ORDER NO.		COMMENTS	
CUST NO: 019191 C.O.D					
TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
0/30/91	11/04/91	EV 10-79	A6834725	700 7MMAG BDL	R 91-22215
ACCESSORIES		SCOPE BASE		L/SIGHTS	

ROM:

SHIP TO:

NORTHCRAFTS FIREARMS
STAR ROUTE BOX 70
HOYES RD
FRIENDSVILLE MD 21531
USA

NORTH CRAFTS FIREARMS
STAR ROUTE BOX 70
HOYES RD
FRIENDSVILLE MD
USA 21531

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 11-11-91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	-----------------------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
UN CONDITION:					
<input type="checkbox"/> NEW	<input type="checkbox"/> SLIGHTLY WORN	<input type="checkbox"/> VERY WORN	<input type="checkbox"/> MISUSED	<input type="checkbox"/> MARRED	

CUSTOMER'S REQUEST

Safety malfunction, causes gun to fire without pulling the trigger.

AIN FAULT

as record; internal trigger parts are not moving freely - trigger
assembly is contaminated with a gummy, sticky residue. Trigger
movement is being impeded by above substance in trigger assembly
and plates. Trigger pull measured at 8.2 pounds; var. lift is .0095"

RTS

Clear trigger assembly if possible if
not, offer new trigger assembly at $\frac{1}{2}$
normal cost, as a gesture of good-
will.

	REPAIRMAN <i>DE</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

REFIRE COPY

RD6925 REV. 7/90

PPS 03675