

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-04497

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 01/31/92	DATE OPENED 02/06/92	DATE CODE DD 7-83	SERIAL NUMBER B6481095	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	BDL
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS		

FROM:

NORTHERN IOWA SPORTS SUPPLY
NORTHERN IOWA SPORT SHOP
12 7TH AVE SE
WAUKON IA 52172

SHIP TO:

NORTHERN IOWA SPORTS SUPPLY
NORTHERN IOWA SPORT SHOP
12 7TH AVE SE
WAUKON IA 52172

CUST NO: 008491 ILIION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE.

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			F1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Trigger assembly has been improperly adjusted outside factory.
1.) trigger pull measured at 2# - well below our minimum spec. (2) insufficient over travel; 3) excessive rear engagement. In addition to the above, the extremely light trigger pull resulted in improper operation of the trigger assembly - the trigger does not re-set upon coming. Trigger assembly not operating properly as received.
Trigger pull 2 pounds; rear-left .011"

PARTS

COMMENTS

Offer replacement trigger assembly at original cost, as a gesture of goodwill. Since rear-engagement has been improperly altered outside factory, we cannot re-adjust in service.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTI
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.

PPS 03677