

RECEIVING AND ESTIMATING REPORT

COMMENTS

1 OF 2

R 93-27807
27807

CUSTOMER ORDER NO.

DATE RECEIVED
12/09/93DATE OPENED
12/16/93DATE CODE
KL 5-91SERIAL NUMBER
7676021

NEW SERIAL NUMBER

MODEL AND GRADE
243

ACCESSORIES

FROM:

NORTHWEST OUTLET
1814 BELKNAP ST
SUPERIOR

WI 54880

SHIP TO:

NORTHWEST OUTLET
1814 BELKNAP ST
SUPERIOR

WI

54880

CUST NO:007887 C.P.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE ☐

FROM DATE

ESTIMATED

VIA UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Product Service

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Unable to reproduce, customer concern. However, disassembly revealed that the firing pin assembly was binding inside bolt body, reason unknown. Repair as follows:

PARTS

COMMENTS

Repair as needed

Replace firing pin, bolt body, & trigger assembly

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 03679