

ORDER
R 93-09805

potter

INITIAL	CUSTOMER ORDER NO.				
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
4/12/93	04/14/93	XU 12-71	6501534		700 22-250 BDL
ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT					

FROM:	SHIP TO:
<i>Set up full</i> NORTHWESTERN INDUSTRIES 416 W MAIN LEON A PYTLIK VALLEY CITY ND 58072	NORTHWESTERN INDUSTRIES 416 W MAIN LEON A PYTLIK VALLEY CITY ND 58072

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				4/29/93	UPS
IN CONDITION					REPAIR CHARGE
NEW					EXCISE 25.00
LIGHTLY WORN					TAX
WORN					INSURANCE
VERY WORN					UPS
UNREPAIRABLE					PARCEL POST
MARRED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1			E1	F1
IGGER GROUP		B2			E2	F2
LT ASSY.		B3		D1	E3	F3
RREL ASSY.		B4		D2	E4	F4
C. ASSY.		B5		D3	E5	F5
OD			C1			
TAL			C2			

UPON receipt of the rifle in inspection. Found per following from user that is about 300 rounds that all 3 trigger adjustment screws have been tampered with outside the factory. No action on adjustment (trigger), but adjust trigger on own adjustment screw.

COMMENTS

Report trigger assembly complete and clean action at 1/2 rounds adjustment test at 100 yds and 200 yds.

[Signature]

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JOB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE