

Customer Complaint
CHIP

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 010030
OUTSIDE WORK: NO DATE: 5-1-72
FROM: ODELL HOWE, CO.
FIRED AMMO TYPE: — GREENSBORO, N.C.
& CONDITION: _____ GUN #: 6489469
PROOF: R.F.P.-H INSP.: 51 TEST: 13 CODE: EU-10/71
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO. APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS. CONNECTOR, SEAR ENGAGE-
MENT = .008 MIN. IS .020 ALSO FOUND METAL CHIP
BETWEEN TRIGGER & CONNECTOR.

COMPLAINT: WILL NOT FIRE.

INCIDENT: FOLLOWS DOWN.

COMMENTS: THE METAL CHIP BETWEEN THE TRIGGER AND
CONNECTOR REDUCED THE CONNECTOR-SEAR ENGAGE-
MENT TO ZERO CAUSING THE FOLLOWS DOWN.