

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-24830

INITIAL

CUSTOMER ORDER NO.

FPS

DATE RECEIVED

11/27/91

DATE OPENED

12/03/91

DATE CODE

XD 12-83

SERIAL NUMBER

B6529376

NEW SERIAL NUMBER

MODEL AND GRADE

700

270 WIN

BDL

ACCESSORIES

W/STUDS

L/REAR SIGHT

FROM:

OLAVARRI, MARTIN
812 EMERALD BAY RD
S LAKE TAHOE
USA

CA 96150

SHIP TO:

OLAVARRI, MARTIN
812 EMERALD BAY RD
S LAKE TAHOE
USACA
96150

CUST NO: 053971 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

A1

B1

B2

B3

B4

B5

C1

C2

D1

D2

D3

D4

D5

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT

Not able to duplicate above complaints. Trigger and safety assembly operates properly in every respect. Trigger pull measured at 5 1/4 pounds; 2-in-lift 210". However, it was noted that trigger assembly and bolt stop were chattering wet with excessive oil. This condition coupled with cold temperatures could conceivably cause internal trigger parts to hang-up.

PARTS

COMMENTS

Offer to clean present trigger assembly or replace trigger assembly at \$100.00 as good-will gesture, if it will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTE

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8

PPS 03698