

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 600
GENERAL CONDITION: GOOD R #: 05361
OUTSIDE WORK: NO DATE: 3-12-71
FROM: OLSON SPTG. GDS.
FIRED AMMO TYPE: - OTTUMWA, IOWA
& CONDITION: _____ GUN #: 33903
PROOF: R.E.P. INSP.: U TEST: 49 CODE: LM-2/65
HEADING: _____ GA./CAL.: 350 MAG.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN, DAMAGED COMPONENTS.

COMPLAINT: MISFIRES, FIRES WHEN GUN IS OPENED.

INCIDENT: FIRING PIN HEAD CATCHES ON HOUSING.

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS NOT DUPLICATED, HOWEVER A MARK LEFT ON THE INSIDE, LEFT REAR CORNER OF THE HOUSING BY THE FIRING PIN HEAD INDICATES AN INTERFERENCE WHICH MIGHT CAUSE SUCH MALFUNCTION. ALSO, SEAR AND SAFETY CAM WERE FOUND TO BE STUCK TOGETHER WITH SOME EXCESSIVELY HEAVY LUBRICANT.