

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R91-26548INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
12/13/91DATE OPENED
12/18/91DATE CODE
DE 9-84SERIAL NUMBER
R6633886

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

ADL

ACCESSORIES

W/SWIVELS

SCOPE BASE

FROM:

ORANGE GROVE FIREARMS
P O BOX 301
ORANGE GROVE
USA

TX 78372

SHIP TO:

ORANGE GROVE FIREARMS
P O BOX 301
ORANGE GROVE
USA

TX 78372

CUST NO: 054944 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

DO received, bolt would not rock at all. I dismantled it with reveals inside of trigger assembly is contaminated with gunning substance. Bear safety cam was sticking to side plate of trigger assembly. Both of action and output of trigger assembly very dirty. Bolt does not operate properly because of gunning substance on surface.

PARTS

COMMENTS

1) Offer new trigger assembly at 1/2 normal cost, as gesture of good-will

2) clean up bottom of barrel of receiver

REPAIRMAN

PROOF

CLEAN

TES.

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8

PPS 03712