

Cust. Compl.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 027329
OUTSIDE WORK: NO DATE: 1-2-73
FROM: OSHMAN'S SPORTING GDS. CO.
FIRED AMMO TYPE: - BEAUMONT, TEXAS.
& CONDITION: _____ GUN #: 6521466
PROOF: R.E.P.-M ^{ASSEMBLER 56} INSP.: 73 TEST: 13 CODE: AW = 3/72
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: CIPROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: GUN FIRED WHEN SAFETY WAS REMOVED

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. THE PRESENCE OF EXCESSIVE LUBRICANT
POSSIBLY CONTRIBUTED TO POOR TRIGGER RETRACT-
ION AND CAUSED FOLLOW DOWN.