

Dear Sirs: Enclosed is my Remington Mountain 9/7/93

Rifle Serial #B6752441 for trigger repair - I sent it to you about 4 years ago for trigger & safety repair.

My problem now is that the safety is at times still and hard to apply and release - Also - when the safety is off - the firing pin will not stay cocked when the bolt is closed - Also - sometimes the firing pin will stay cocked when the bolt is closed - and then release itself without the trigger being pulled - it scared me yesterday pretty badly when I was sighting it in - I cocked the rifle - and was getting ready to put the forend on the rest and the firing pin released itself - Thank God it was aimed down range -

* Please do not repair this trigger assembly - Please install and adjust a new trigger assembly -

Thank You for your help - I have 6 other Remington 700's - Some over 30 years old - and this is the first one I have had trouble with -

* If possible - could I have it ⁽⁶⁰⁰⁾repaired and back to me by 10/8/93 - so I can use it for Elk and Deer this year in Colorado - Thank You

ERIK AND BARBARA OSTLY
RT. 4 BOX 556
CALIF. HOT SPRINGS, CA 93207

ERIK OSTLY
RT. 4 BOX 556
44071 Parke Pass Drive
CA. Hot Springs, CA. 9.