

P.I. YES GUN EXAMINATION REPORT NUMBER: 180 MODEL: 700 A DL
 GENERAL CONDITION: GOOD R #: 28870
 OUTSIDE WORK: SCOPE BASE ADDED DATE: 11-2-79
 FROM: OZARK SHOOTERS IN.
 FIRED AMMO TYPE: NOT KNOWN 1719 COLLEGE SPRINGS, ARK.
 & CONDITION: _____ GUN #: A6524535
 PROOF: REP INSP.: 62 TEST: 111 CODE: PO = 11-77
 HEADING: NOT ABLE TO CHECK GA./CAL.: 222
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: 11/30/79
 CHAMBER: OK APPROVED: 11-30-79
 TEST: _____ APPROVED: 11/30/79
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 11-30-79
TRIG PULL

COMPLAINT: FIRED WHILE UNLOADING
CUSTOMER STATES DEFECTIVE SEARS IN RIFLE

INCIDENT: _____

COMMENTS: Trigger assembly adjusted & resealed outside
of Remington as evidenced by yellow sealant on
screws. Sear engagement & trigger pull out of
Remington Specs. Lift will follow down due to
inadequate sear engagement and trigger pull.
Sear lift .0115