

RECEIVING AND ESTIMATING REPORT

INITIAL	CUSTOMER ORDER NO.	ATTN: DENNIS SANITA			
FPS					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/16/93	11/19/93	LX 2-73	6621627		700 243 WIN ADL
ACCESSORIES		HARD CASE SCOPE BASE			

FROM:	SHIP TO:
<i>Red Supra</i> PALMOUR, HAROLD M. 4565 FM 3126 LIVINGSTON TX 77351	PALMOUR, HAROLD M. 4565 FM 3126 LIVINGSTON TX 77351

CUST NO: 087630 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA
				UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☒ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED				REPAIR CHARGE <i>2</i> EXCISE TAX INSURANCE UPS PARCEL POST TOTAL <i>3</i>

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Sold mfg. 1973. Upon receipt rifle inoperative. trigger would not move or reset, bolt stop also would not move upon closed. Examination revealed action and trigger assembly covered with a heavy greasy, and sticky substance. internal parts also gummed up.*

PARTS *Trigger has been removed from the trigger adjustment & stop screw indicating they have been tampered with outside the factory. Poor maintenance.*

COMMENTS *Replace trigger mechanism. Clean action at 1/2 normal speed. Cost, no question of good work.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET
GALLERY TESTER	DATE	DATE	DATE	DATE

5398 8000 0770 4374
 App Jan 95
 Phone 409-566-4033