

file

RECEIVING AND ESTIMATING REPORT

COMMENTS

L SIGHTS

INITIAL CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

03/09/89

03/14/89

DI 9-88

A6355272

700

7MM

MAG

R

89-0969E

ACCESSORIES

L/MAG BOX

L/WOOD

L/FOLLOWER

L/MAG SPRING SCOPE BASE

FROM:

HERB PARKHURST
EMORE ROAD
MORRISVILLE VT 05661

SHIP TO:

HERB PARKHURST
EMORE ROAD
MORRISVILLE VT 05661

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

V416079153

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☒ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"The gun fired into the ground when the safety was released"

MAIN FAULT

- 1) Trigger has been improperly adjusted outside factory.
- 2) Adjustment screw has been broken
- 3) There is no spring action to cause trigger to retract - engagement is inconsistent because of this - sometimes rifle will not lock.

PARTS

Send repair quotation to repair rifle properly.

3/17/89

JOS

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

REV. 6

PPS 03787