

REPAIR GUN UPDATE FUNCTION: N (N)EXT (P)REV (U)PDATE (I)NO (E)XACT 03/31/94  
ENTER REPAIR NUMBER -----> 9203077 13 45 54  
SERIAL NO: A6346902 NEW SERIAL NO: MODEL: 700  
FROM: (CUST NUM: 056921 ) PAYNECLAYT GA/CAL: 30-06  
PAYNE, CLAYTON L TYPE: ADL  
1360 GIBSON DRIVE ACCESSORIES: W/STUDS

BIRMINGHAM AL 35214  
SHIPPED TO:

DATE CODES: WI  
OTHER ACCESSORIES:

COMMENTS: W/LEUPOLD 2X7 SCOPE & SEE THRU SCOPE MNTS

DATES: TO FROM  
RECEIVED 01 17 92 GALLERY 03 12 92 03 16 92 ENTERED BY: FPS  
OPENED 01 24 92 PROD SERV 02 18 92 02 20 92 REPAIRMAN: EZ  
ESTIMATED 02 26 92 TAG GUNS 00 00 TYPYST:  
PROMISED 00 00 00 REJECTED 00 00 CORRESPONDENT:  
GO AHEAD 00 00 00 CASH RECEIVED:\$ 0.00 BILL TYPE: D  
SHIPPED 03 25 92  
BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9203077 CHARGE (AWAIT RESP) CREDCRD INV PRI 03/31/94  
CUSTOMER NAME: PAYNE, CLAYTON L 13 46 22  
=====

REQUEST: 3 TIMES, FIRED WHEN SAFETY RELEASED  
MAIN FAULT: CANNOT DUPLICATE COMPLAINT AFTER MANY ATTEMPTS - REMOVAL OF  
BARRELED ACTION FROM STOCK REVEALED DIRT & EXCESSIVE OIL ON  
UNDERSIDE OF METAL - TRIGGER ASSEMBLY IS EXCESSIVELY OILY &  
DIRTY ALSO -

DATE OF MFG: 08-88

PARTS: \$ 0.00 1 26345 TRIGGER ASSEM RH  
LABOR: \$ 0.00 REPLACE TRIGGER ASSEM AT 1/2 NORMAL COST, AS A GESTURE  
\$ 0.00 OF GOOD WILL -  
\$ 25.00 REPAIR CHARGE -  
\$ 0.00 TEST  
\$ 0.00 EZ/HAR  
\$ 0.00 \* RETURN SCOPE & MT. IN CABINET

1360 GIBSON &  
B'HAM, AL 35214