

Cust. Complaint.

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: Good R #: 27191
OUTSIDE WORK: SCOPE MOUNTED DATE: 12-27-71
FROM: PECOS SPT GDS.
FIRED AMMO TYPE: - PECOS, TEXAS
& CONDITION: _____ GUN #: 6383773
PROOF: PEP-A ^{ASSEMBLER 47} INSP.: 73 TEST: 27 CODE: RT = 11/70
HEADING: O.K. GA./CAL.: 2506 REM
BREECH OPENING: - CHECKED BY: C. PRITCHER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-CONNECTOR ENGAGEMENT .030. TRIGGER PULL 2 1/2
POUNDS. STOCK ETC. NOT INCLUDED. MARK ON TRIGGER
SIDE INDICATES POSSIBLE BIND ON TRIGGER GUARD.

NO STOCK, MAGAZINE OR MAGAZINE FOLLOWER'S
SPRING.

COMPLAINT: DISCHARGED WHEN SAFETY WAS MOVED FROM SAFE
TO FIRE POSITION.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS NOT DUPLICATED,
HOWEVER IT MAY HAVE BEEN CAUSED BY TRIGGER BINDING
IN THE TRIGGER GUARD.