

P.I. No GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL  
GENERAL CONDITION: NEW R #: 13298  
OUTSIDE WORK: No DATE: 6-29-71  
FROM: J.C. PENNEY  
FIRED AMMO TYPE: - KING OF PRUSSIA, PA.  
& CONDITION: \_\_\_\_\_ GUN #: 6274124  
ASSEMBLER 79  
PROOF: R.E.P.-E INSP.: 58 TEST: 13 CODE: DS = 9/69  
HEADING: O.K. GA./CAL.: 270  
BREECH OPENING: \_\_\_\_\_ CHECKED BY: C. PROSSER  
RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
CHAMBER: O.K. APPROVED: \_\_\_\_\_  
TEST: No APPROVED: \_\_\_\_\_  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

NO BROKEN OR DAMAGED COMPONENTS.

TRIGGER CONNECTOR - SEAR ENGAGEMENT .010 (.020 MIN.)

TRIGGER PULL 4 1/2 LBS. A SMALL METAL CHIP CAUGHT  
BETWEEN TRIGGER CONNECTOR & TRIGGER.

COMPLAINT: "FIRES DURING SHELL EXTRACTION"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE  
DUPLICATED. THE UNDER MIN. ENGAGEMENT WAS CAUSED  
BY THE METAL CHIP (HELD IN PLACE BY A PROTECTIVE  
COATING APPLIED BY THE CUSTOMER) PROBABLY CAUSED  
THE MALFUNCTION.