

P.I. / F.O. GUN EXAMINATION REPORT NUMBER: 202

MODEL: 600

GENERAL CONDITION: Fair

R # : 33722

OUTSIDE WORK: Recoil P.L. .0075

DATE: 12-15-79

202 202 202 202 202 202 202 202 202 202

FROM: 100 300 300 300 300 300 300 300 300 300

FIRE AMMO TYPE: NOT KNOWN

300 300 300 300 300 300 300 300 300 300

& CONDITION: _____

GUN # : 6670572

PROCP: 800 INSP.: 98 TEST: 70

CODE: XX 12-73

HEADING: 38

GA./CAL.: 243

BREECH OPENING: OK

CHECKED BY: M Hardy

RECOIL SHOULDERS: OK

APPROVED: 1/29/80

CHAMBER: OK

APPROVED: 1/29/80

TEST: _____

APPROVED: 1/29-80

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: 1/29-80

TEST - DELETED, CUT OUT BY RECOIL P.L. .0075

COPIED FILES RECOIL P.L. .0075

" 1/2" on trigger assembly

COMPLAINT: SHOT HOLE THROUGH FLOOR

INCIDENT: _____

COMMENTS: Passer tick test. See list .0075"

Engagement OK, adjusting screws have not been
loosened with.

Wanted to produce only trigger assembly material