

*Not too Customer Complaint*

P.I. No GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 VARMINT  
GENERAL CONDITION: NEW R #: 014137  
OUTSIDE WORK: FRONT TRIGGER ADJUSTING DATE: 7-13-72  
SCREWS ADJUSTED. FROM: H.L. PETERS INC.  
FIRED AMMO TYPE: — BUFFALO, N.Y.  
& CONDITION: \_\_\_\_\_ GUN #: 6519891  
PROOF: R.E.P.-M INSP.: 48 TEST: 44 CODE: LW = 2/72  
HEADING: — PW = 6/72  
BREECH OPENING: — G.K./CAL.: 25-06 REM.  
RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER  
CHAMBER: O.K. APPROVED: \_\_\_\_\_  
TEST: No APPROVED: \_\_\_\_\_  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

CONNECTOR - SEAR ENGAGEMENT .010 (MIN. = .020) TRIGGER  
ADJUSTING SCREW BACKED OUT ELIMINATING SPRING TENSION  
REQUIRED TO RETRACT TRIGGER & TRIGGER CONNECTOR.

COMPLAINT: FIRES WHEN CLOSING BOLT

INCIDENT: FOLLOW DOWN

COMMENTS: APPARENTLY THE CUSTOMER, ATTEMPTING TO  
ADJUST THE TRIGGER PULL, BACKED THE ADJUSTING  
SCREW OUT TOO FAR WHICH ELIMINATED ALL SPRING  
TENSION. WITHOUT THIS, THE TRIGGER AND CONNECTOR  
FAILED TO RETRACT RESULTING IN FOLLOW DOWN.