

NO. 100 4/78

Remington.

REPAIR

RECEIVED 3/1/88

25 ARMS SERVICE FILE

IMMEDIATE REPLY & CHECK

Remington.

REMINGTON ARMS COMPANY, Inc. OR R.O.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

PLEASE MAIL
REMITTANCE
TO BOX CHECKED

☐

BRIDGEPORT, CONN. 06402

☒

ELIOT, N. Y. 13357

INVOICE NO R-88-05101

INVOICE DATE

SHIP TO

SOLD
TO

False River Sports Shop, Inc.
211 W. Main St.
New Roads LA 70760

OUR ORDER NO R-88-05101-700

OUR ORDER NO

SHIP VIA UPS

DD 9-86

700 7MM MAG. BDL B6735295
W/studs, L/sights

COMPLAINT: When I pushed the safety forward, the rifle went off.

MAIN FAULT: Trigger assem. is full of rust & paint-assem. is so full of rust & paint that the trigger will not consistently return under sear-safety cam on cocking Rifle has been very poorly maintained.

1. 26345 Trigger assem. B.O.C.
2. Polished chamber
3. Test

TOTAL REPAIR CHARGE 40.00

INSURANCE

PARCEL POST

UPS

4.09

TOTAL CHARGES

44.09

THE REMINGTON ARMS COMPANY, INC. MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, FOR THE MERCHANTABILITY OF THE GOODS OR SERVICES PROVIDED HEREON.

THE REMINGTON ARMS COMPANY, INC. MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, FOR THE MERCHANTABILITY OF THE GOODS OR SERVICES PROVIDED HEREON.

THE REMINGTON ARMS COMPANY, INC. MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, FOR THE MERCHANTABILITY OF THE GOODS OR SERVICES PROVIDED HEREON.

THE REMINGTON ARMS COMPANY, INC. MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, FOR THE MERCHANTABILITY OF THE GOODS OR SERVICES PROVIDED HEREON.

THE REMINGTON ARMS COMPANY, INC. MAKES NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, FOR THE MERCHANTABILITY OF THE GOODS OR SERVICES PROVIDED HEREON.

CUSTOMERS SIGNATURE ▶

JUN 02 1988

CLEAN TEST TARGET

REPAIRMAN

OFFICE COPY

REM 725 REV. 3/84