

RD 5396 - 8/78

Remington.



RECEIVED 1/1/88

20 ARMS SERVICE FILE

AWAIT REPLY & CHECK

REMINGTON ARMS COMPANY, INC. OR N.O.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

Remington.



PLEASE MAIL
REMITTANCE
TO BOX CHECKED

☐

BRIDGEPORT, CONN. 06602

☒

ILION, N. Y. 13357

INVOICE NO R-88-05101

INVOICE DATE

SHIP TO

SOLD
TO

False River Sports Shop, Inc.
211 W. Main St.
New Roads LA 70760

OUR ORDER NO R-88-05101-700

OUR ORDER NO

SHIP VIA UPS

DO 9-86

700 7MM MAG. BDL B6735295
W/studs, L/sights

COMPLAINT: When I pushed the safety forward, the rifle went off.

MAIN FAULT: Trigger assem. is full of rust & paint-assem. is so full of rust & paint that the trigger will not consistently return under sear-safety cam on cocking Rifle has been very poorly maintained.

1. 26345 Trigger assem. B.O.C.
2. Polished chamber
3. Test

TOTAL REPAIR CHARGE 40.00

INSURANCE

PARCEL POST

UPS

4.09

TOTAL CHARGES 44.09

THE REMINGTON ARMS COMPANY, INC. IS NOT RESPONSIBLE FOR THE RETURN OF A RIFLE OR OTHER FIREARM IF IT IS RETURNED WITHOUT THE FIRST COPY OF THIS INVOICE.

IF THE RIFLE OR OTHER FIREARM IS RETURNED WITHOUT THE FIRST COPY OF THIS INVOICE, THE REMINGTON ARMS COMPANY, INC. WILL NOT BE RESPONSIBLE FOR THE RETURN OF THE RIFLE OR OTHER FIREARM.

IF THE RIFLE OR OTHER FIREARM IS RETURNED WITHOUT THE FIRST COPY OF THIS INVOICE, THE REMINGTON ARMS COMPANY, INC. WILL NOT BE RESPONSIBLE FOR THE RETURN OF THE RIFLE OR OTHER FIREARM.

CUSTOMERS SIGNATURE

JUN 12 1988

CLEAN TEST TARGET

REPAIRMAN

OFFICE COPY

REV. 3.88