

ING AND ESTIMATING REPORT

CUSTOMER ORDER NO.

ORDER
R92-27422

D	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
2	2/14/92	RY 11-74	6800645		700 30-06 BDL

W/STUDS

SHIP TO:

PITTS/WILLIAM L
8789 LEE RD
LITHIA SPRINGS

GA 30057

PITTS/WILLIAM L
8789 LEE RD
LITHIA SPRINGSGA
30057

CUST NO: 071847 C.O.D

BER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

ON	VORN	IN	TABLE	REPAIR CHARGE	EXCISE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
										25.00

UPS
C.O.D.

CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
	A1	B1				
OUT		B2			E1	F1
		B3			E2	F2
Y.		B5			E3	F3
				D2	E4	F4
			C1	D3	E5	F5
			C2			

Unable to duplicate Customer Complaint. However, upon inspection, gummy brown substance found on bolt stop and on trigger assembly. Gun is not responsive. For now, cleaning kit, and trigger assembly replaced.

COMMENTS

Based on condition, offer to replace trigger assembly at the lowest cost, as feature of good will.

Mr. Pitts approved per phone 1/5/93

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92