

RECEIVING AND ESTIMATING REPORT

AL IB		CUSTOMER ORDER NO.		COMMENTS	
RECEIVED 1/09/90	DATE OPENED 10/16/90	DATE CODE	SERIAL NUMBER A6428840	MODEL AND GRADE 700 30-06 BDL/LH	ORDER R 90-268

ESSORIES

L/ STUDS

DM:

PORTER, KENNETH
A.O. PORTER CO
SCULPS HILL RD
AUBURN PA 17922

SHIP TO:

PORTER, KENNETH
A.O. PORTER CO
SCULPS HILL RD
AUBURN

PA
17922

QUANTITY	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
----------	--------------------	--------------------------------	------------	------------	-----------	-----

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☒ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"000 gun fired twice when I pushed the safety off"

FAULT Trigger assembly is rusted - exterior & interior - will have been at sometime and was not properly maintained - bottom of handle has rust.

Send repair quotation to replace trigger assembly at 2. nominal price as gesture of good-will.		REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTERN
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6,