

Find:

When I first examined this gun, the trigger was very difficult to pull. It would stay retracted, and gun, of course, would not cock. Suddenly little pieces of something were visible along side trigger. I got these pieces out, one at a time, and they proved to be pieces of trigs, (in plastic envelope).

Now, trigger seems to work normally. I did not measure bar lift, or disassemble fire control. I did remove action from stock, but could find no more debris.

Trigger pull - 4#
Bar lift - 0.012"

Trigger pull of solid fuel
oil & pin needles