

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-24042

INITIAL

CUSTOMER ORDER NO.

W/SEE THRU MTS

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/20/91

11/25/91

6887265

700 30-06

ACCESSORIES

W/STUDS

OZ 7-75 2ND TIME

FROM

SHIP TO

QUINTON, JAMES F, JR
30 STONYBROOK RD
SANFORD
USA

ME 04073

QUINTON, JAMES F, JR
30 STONYBROOK RD
SANFORD
USA

ME 04073

CUST NO: 053521 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

12/3/91

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☒ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY

B3

BARREL ASSY

B4

REC. ASSY

B5

WOOD

C1

METAL

C2

MAIN FAULT

Can find no fault - cannot duplicate complaint; up
cannot find no malfunction in the above manner.

Disassembly of rifle revealed rear engagement has been altered out
of factory; barrel is excessive.

Trigger pull - 4 1/2 pounds; rear lift - .008"

PARTS

COMMENTS

Rifle can be returned as-is
Offer new style trigger assembly
no bolt-locks, at 1/2 normal cost
as a gesture of good-will, if it will
better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PA

GALLERY TESTER

DATE

DATE

DATE

DATE

DA

OFFICE COPY

RD5925 RE

PPS 04006