

Don
Sperry Electric
RT 109
Searched me 04012

Remington Arms Co. Problem

Customer Service

to remedy

Don't let for safety

Dear Sir,

I am returning the enclosed
Remington 700 A02, 30-06, Serial 6887265
for repair of an extremely dangerous defect
in the firearm's safety mechanism. On three
separate occasions the gun has discharged
when the safety was moved to the fire
position. I have had the gun examined
by a local gunsmith who tightened up the
safety but could find no other problem.
The gun has since malfunctioned since the
"repair". Interestingly the gun does not always
exhibit the problem. Several boxes of cartridges
were fired between each incident without
a discharge. If possible please do not adjust
the trigger pull. At its present pull,
with my favorite load, the rifle shoots $\frac{1}{2}$ "
groups at 100 yards.