

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-20714

CUSTOMER ORDER NO.

ATTN J STEKL BOTTLE F OF MTS ONLY
CLASSIC

E RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

9/01/92

10/08/92

01 7-88

C6280426

700 35

WHELEN

ESSORIES

W/STUDS

SCOPE BASE

M:

SHIP TO:

RAISLER, LOU
8546 W HOMOSASSA TRAIL ST #3
HOMOSASSA FL 32448

RAISLER, LOU
8546 W HOMOSASSA TRAIL ST #3
HOMOSASSA FL 32448

L

CUST NO:067857 C.O.D.

QUANTITY

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION

NEW

SLIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

DARRIED

REPAIR CHARGE:

EXCISE:

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

LE

A1

B1

GER GROUP

T ASSY.

B3

REL ASSY.

B4

D1

ASSY.

B5

D2

JD

C1

D3

AL

C2

FAIR

Cannot duplicate complaint after many attempts - Trigger assembly operating properly. However, disassembly of the revealed trigger assembly components have been tampered with outside factory (sealant missing from all vent screws) 1) insufficient rear engagement, 2) insufficient over travel engagement 4# rear off 0.010" stock is radial at front guard screw location - insufficient clearance for screw

COMMENTS

1) Offer replacement trigger assembly at nominal cost, as good will gesture

2) Replace stock at N/C

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 04020