

CEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 74-13864

CUSTOMER ORDER NO.

ATTN: TOM NAGLE

RECEIVED
7/21/74DATE OPENED
04/22/74DATE CODE
EX 10/73SERIAL NUMBER
6682577

NEW SERIAL NUMBER

MODEL AND GRADE

100 30-06

3PK6 BDL

ISSUES W/STUDS

SHIP TO:

KAND, SAMUEL
1427 HARLANSBURG RD
NEW CASTLE

PA 16101

KAND, SAMUEL
1427 HARLANSBURG RD
NEW CASTLE

PA

16101

CUST NO: 096388 C.U.D.L.

UNIT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION

EW

GHTLY WORN

ORN

ERY WORN

NREPAIRABLE

ARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

TOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

E

A1

B1

GER GROUP

B2

E1

F1

ASSY.

B3

E2

F2

REL ASSY.

B4

D1

E3

F3

ASSY.

B5

D2

E4

F4

D

C1

D3

E5

F5

AL

C2

FAULT

COMMENTS

Mfg date 10/73 Trigger functioned normally in every respect
 per recd. some built on bot. under fire and. Factory silent
 missing from screw slot on over travel screw. Bolt stop has
 sticky gummy residue on it. Inside of trigger housing and
 both sides of trigger were rusty. Exchange trigger ASSY
 at no charge strictly as a gesture of good will. Note Trigger
 ASSY should be lubricated with Rem-ol. periodically to
 prevent rusting and to
 avoid lubrication build up.

Trigger pull measured 4 1/2 LBS as
 recd and here left is .0065

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 04039