

RECEIVING AND ESTIMATING REPORT

COMMENTS

STEKL

ORDER
R 92-1778

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

PA 6-80

SERIAL NUMBER

B6225317

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

ADL

ACCESSORIES

FROM:

RENNICK, R J
9555 BROWN
BEAUMONT

TX 77707

SHIP TO:

RENNICK, R J
9555 BROWN
BEAUMONT

TX 77707

CUST NO: 062197 C.D.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

As received, trigger assembly and bolt stops were inoperative. Disassembly of rifle, checked then reassembled above counterfitted with a gunsmith's improvement which did not allow the bolt stop lever or safety cap to move. The rifle would not lock upon closing the bolt. The firing pin assembly followed down. Improper maintenance.

PARTS

COMMENTS

Send quote for thorough cleaning and new blued assembly (to normal cost, as getting good deal)

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 04147