

# RECEIVING AND ESTIMATING REPORT

COMMENTS

|                        |                         |                      |                          |                                |                     |  |  |  |
|------------------------|-------------------------|----------------------|--------------------------|--------------------------------|---------------------|--|--|--|
| TIAL<br>JM             | CUSTOMER ORDER NO.      |                      |                          |                                |                     |  |  |  |
| TE RECEIVED<br>4/16/91 | DATE OPENED<br>04/19/91 | DATE CODE<br>LZ 2-75 | SERIAL NUMBER<br>6838472 | MODEL AND GRADE<br>700 308 ADL | ORDER<br>R 91-09382 |  |  |  |
| CESSORIES<br>W/STUDS   |                         |                      |                          |                                |                     |  |  |  |

OM: RICHARDS, HAROLD J  
401 CLEVELAND AVE  
ISHPEMING MI 49849

SHIP TO: RICHARDS, HAROLD J  
401 CLEVELAND AVE  
ISHPEMING MI 49849

|              |                    |                                |            |            |           |            |
|--------------|--------------------|--------------------------------|------------|------------|-----------|------------|
| COUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED | VIA<br>UPS |
|--------------|--------------------|--------------------------------|------------|------------|-----------|------------|

|            |     |           |     |             |       |
|------------|-----|-----------|-----|-------------|-------|
| AIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|------------|-----|-----------|-----|-------------|-------|

JN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST *11.00 rifle has fired three times when line switched the safety lever from safety to fire.*

IN FAULT *No fault found - cannot duplicate complaint. Trigger and safety assembly operate properly in safety request. Trigger pull 4 1/2 pounds; head lift .0095"*

TS *Offer to return rifle as-is or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.*

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV. 7/90

PPS 04155