

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R 94-11245	
INITIAL		CUSTOMER ORDER NO.					
FPS							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
03/29/94	03/29/94	BI 1-88	A624866		700 222 REM ADL		
ACCESSORIES		L/REAR SIGHT					
FROM:				SHIP TO:			
JOE RIGGS SPORTING GOODS 137 E HIGH ST WAYNESBURG PA 15370				JOE RIGGS SPORTING GOODS 137 E HIGH ST WAYNESBURG PA 15370			
CUST NO 905657 CL O.D.							
ACCOUNT NUMBER		ACCOUNT NUMBER NC		FROM DATE		ESTIMATED	
						VIA UPS	
GUN CONDITION						REPAIR CHARGE \$7.00	
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	
CUSTOMER CONCERN		AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE		B1					
TRIGGER GROUP		B2	functionally when bolt closed				F1
BOLT ASSY.		B3					F2
BARREL ASSY.		B4		D1			F3
REC. ASSY.		B5		D2			F4
WOOD			C1	D3			F5
METAL			C2				
MAIN FAULT <i>Wp 1488 Upon receipt, we were unable to duplicate the customer's complaint. Examination revealed that the trigger mechanism and trigger stop screws have been re-set without the proper 1/8 inch interval. correct was applied to our original claim. The action is correct and is being given.</i>							
PARTS				COMMENTS			
				<i>Refr. needs a good cleaning</i> <i>Refr. complete trigger assembly</i> <i>& clean action at 1/2 normal</i> <i>replacement cost is \$100.00</i>			
GO ahead				PROOF CLEAN TEST TARGET PATTERN FB. DATE DATE DATE DATE DATE DATE			

OFFICE COPY

RD6925 REV. 1/94