

RECEIVING AND ESTIMATING REPORT

CUST NO: 047992 C.O.D		COMMENTS ENTIRE GUN IS PAINTED	
INITIAL CS	CUSTOMER ORDER NO.		
DATE RECEIVED 8/20/91	DATE OPENED 08/22/91	DATE CODE DB-1/F1	SERIAL NUMBER B6324614
ACCESSORIES W/STUDS		MODEL AND GRADE 700 308	ORDER R 91-16474
SCOPE BASE		L/SIGHTS	

FROM:	SHIP TO:
ROBINSON, MARK RT 3 BOX 181A CAMERON USA	ROBINSON, MARK RED X MOTORE 509 NORTHLAND DR CAMERON USA
MD 64429	MD 64429
ACCOUNT NUMBER	ACCOUNT NUMBER N/C
WRITE ☐	CLEAN/TEST
PROM. DATE	ESTIMATED 9-9-91
	VIA UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

When safety is disengaged rifle sometimes fires, when closing bolt it will discharge.

AIN FAULT

Cannot duplicate above complaints. However, trigger assembly has been improperly adjusted outside factory as evidenced by redout missing from adjustment screw. Trigger pull below spec at 24. #2) over-travel insufficient. Cam-follower has been installed in after-market synthetic stock - safety lever will not move fully rearward because of contact in stock inletting.

Send repair quotation for new trigger assembly.

REPAIRMAN DE	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD4923 REV. 7/90

PPS 04207