

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 92-16159INITIAL  
FPS

CUSTOMER ORDER NO.

W/RUBBER BOOT

DATE RECEIVED  
08/03/92DATE OPENED  
08/12/92DATE CODE  
LD 2-77SERIAL NUMBER  
A6413960

NEW SERIAL NUMBER

MODEL AND GRADE  
700 30-06

ADL

ACCESSORIES SCOPE BASE HARD CASE

FROM:

ROGERS, ROY  
8700 E. CO. RD. 85  
MIDLAND

TX 79701

SHIP TO:

ROGERS, ROY  
8700 E. CO. RD. 85  
MIDLANDTX  
79701

CUST NO: 064753 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            | A1   | B1       |        |          |     |         |
| TRIGGER GROUP    |      | B2       |        |          |     |         |
| BOLT ASSY.       |      | B3       |        |          |     | F2      |
| BARREL ASSY.     |      | B4       |        | D1       | E3  | F3      |
| REC. ASSY.       |      | B5       |        | D2       | E4  | F4      |
| WOOD             |      |          | D1     | D3       | E5  | F5      |
| METAL            |      |          | D2     |          |     |         |

MAIN FAULT

Rifle will malfunction as described above. However, disassembly of rifle revealed trigger assembly has been improperly adjusted on the factory — such engagement is unusual and was checked in down trigger pull — 5 1/2 lb; rear lift — 0.006"

PARTS

COMMENTS

Rifle assembly has been tampered with outside factory, offer new trigger assembly at \$100.00 plus cost of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTE

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 1

PPS 04227