

RECEIVING AND ESTIMATING REPORT ✓

INITIAL CS		CUSTOMER ORDER NO.		COMMENTS ATTN J STEKL			
DATE RECEIVED 10/04/90	DATE OPENED 10/12/90	DATE CODE KY 5-74	SERIAL NUMBER 6749628QQQ	MODEL AND GRADE 700 30-06 ADL		ORDER R 90-26	
ACCESSORIES L/SIGHTS		SCOPE BASE					

FROM:

ROYAL ARMS
5608 KITSAP WAY SUITE 1
BREMERTON WA 98312

SHIP TO:

ROYAL ARMS
5608 KITSAP WAY SUITE 1
BREMERTON WA
98312

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☒ MARRED

CUSTOMER'S REQUEST

"It has had 3 accidental discharges when safety is released"

MAIN FAULT: Cannot duplicate complaint; Trigger assembly and safety operate properly. However, assembly contains an excessive amount of lubrication (oil) - a cold temperature, this accumulation could cause trigger parts to freeze and cause problems. Trigger pull 4 pounds, rear-leaf .008"

PARTS: Offer to clean present trigger assembly. If it will better restore confidence in the rifle, offer to replace trigger assembly at 1/2 normal price as gesture of good-will.

10/15/90
JH

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY