

RECEIVING AND ESTIMATING REPORT

#36

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS	
DATE RECEIVED 10/25/90	DATE OPENED 10/29/90	DATE CODED KI 5-88	SERIAL NUMBER C4252382	MODEL AND GRADE 700 30-06	ADL/LS
ACCESSORIES 47 STUDS		ORDER NO.			

FROM:		SHIP TO:	
RUTTY, STEPHEN E RD #2 BOX 240 CANTON PA 17724		RUTTY, STEPHEN E RD #2 BOX 240 CANTON PA 17724	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE ESTIMATED VIA UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☒ LIKE NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"is moving the safety across the rifle to fire"

MAIN FAULT

Tripin assembly rusted from unknown source.
Internal tripin parts not moving freely

PARTS	Replace tripin assembly at no-charge, as gesture of good-will				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE