

RECEIVING AND ESTIMATING REPORT

H93-17685

INITIAL FPS	CUSTOMER ORDER NO.	W/PACHMAYR RECOIL PAD			
DATE RECEIVED 08/20/93	DATE OPENED 08/25/93	DATE CODE 84	SERIAL NUMBER B6626671	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN ADL
ACCESSORIES SCOPE BASE					

FROM:

SHIP TO:

SATIN SEAR PISTOLSMITH
424A PECAN DR.
ALEDO

TX 76008

SATIN SEAR PISTOLSMITH
424A PECAN DR.
ALEDO

TX 76008

CUST NO: 082651 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 9-9-93	VIA UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			☐ EXCISE ☐ TAX ☐ INSURANCE ☐ UPS ☐ PARCEL POST ☐ TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL						

MAIN FAULT

Unable to disassemble certain screws, however, the
 disassembly was not that bad 3 important screws have had the
 correct screws, indicating they have been replaced with correct the factory
 condition of the bolt not working under operation, a screw, not bad, but it is
 the same as the one that was replaced.

REPAIRMAN COMMENTS
 The trigger group was replaced
 at the normal replacement cost
 to get the gun back in
 good shape.

REPAIRMAN CC	PROOF	CLEAN	TEST	TARGET	Pi
GALLERY TESTER	DATE	DATE	DATE	DATE	0

OFFICE COPY

R069251