

bcc: Arms Service K89-24640
Hold for reply
J. Hutton & Bill Ericson

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

October 23, 1989

Mr. Albert Saviano
278 McKinley Pl.
Ridgewood, NJ 07450

Dear Mr. Saviano:

Examination has been completed on the Model Seven 7mm-08 Rem. caliber rifle, serial number 7650523, that you returned to us a short time ago because, the rifle fired when you started to move the safety to the "Safe" position.

The returned firearm, which was produced in August of 1988, has been thoroughly examined and found to contain our high-pressure proof test, gallery test and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections before being shipped from our factory.

The general condition of the gun appeared to be excellent. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the condition that you reported. Many attempts were made to cause the rifle to fire upon movement of the safety (in both directions) without success. Trigger pull was measured to be 4 pounds, and the sear-lift with the safety in the "safe" position was well within specifications at .011". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Since we found the firearm to function correctly in every way, we are prepared to return it to you in its present condition. How-