

RECEIVING AND ESTIMATING REPORT ✓

COMMENTS

ATTN: DENNIS SANITA

AL CUSTOMER ORDER NO.

P

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
1/26/90	03/01/90	WU 10-71	6486174	700 30-6 BDL	R 90-08204
ACCESSORIES W/STUDS SCOPE BASE					

DM:

LARRY SCHENEWERK
615 TERRACE DR
CALIFORNIA HQ 65018

SHIP TO:

LARRY SCHENEWERK
615 TERRACE DR
CALIFORNIA

HQ
65018

QUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

OWNER'S REQUEST

accidental firing

FAULT

*upper assembly / full stop completely contaminated with some
firing substance. Bolt will not move out of hole, firing pin
does not work in cocking cam.*

*1) Per customer's request during phone
conversation 3/6/90 - replace trigger
assembly with new-style safety -
no full body at N/C*

2) Large 10-15 handling plus return postage.

*3) Send new Dennis's manual with rifle
when returned. 3/4/90
JCS*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

REV. 6/88