

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

September 7, 1990

Mr. Tom Scheuer
527 Elizabeth St.
Mishicot, WI 54228

Dear Mr. Scheuer:

We are in receipt of the Model 700 270 Win. caliber rifle, serial number B6778672, that you sent to us after experiencing a problem while shooting Remington factory loaded ammunition.

We were indeed sorry to learn of your having a problem while using our products, and that you were slightly injured as a result of it.

Examination of the returned fired casing indicates that either the round contained excessive pressure, or, the head of the shell was too soft and allowed it to expand and drop the primer. We are not able to make a positive determination at this plant site, but are forwarding the case to our Lonoke, Arkansas ammunition facility for further inspection.

At this time, we do not recommend that you fire any of the remaining ammunition, and ask that you forward it to our Lonoke plant for examination, as follows:

Remington Arms Co., Inc.
Attn: W.T. Smith
Product Service
1-40 & Remington Road
Lonoke, Arkansas 72086

Upon receipt, Mr. Smith will send you a check for some replacement ammunition.