

cause excess head space, and also that I should send the cartridge back to the Remington Arms Co. because this was a factory load. I have never shot reloads. I then took my gun to a gunsmith, who removed the splinter from the ejector pin, and also checked the headspace. He used what he called a no-go gauge, which he told me you should not be able to close the bolt on, which he did quite easily. He told me to send the gun back to the Remington Company because it might need a new barrel, and also to have the bolt checked over.

My gun is a Model 700 ADL, 270 Win., Serial no. B6778672. I hope this will not take more than a few weeks, as we are going on a Wyoming hunt in Sept.

I was also wondering if the rest of this box of cartridges is safe to use, or if I should throw them out. I have