

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-27579

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED 12/08/93 DATE OPENED 12/15/93 DATE CODE RX 11-72 SERIAL NUMBER 276 NEW SERIAL NUMBER 700 MODEL AND GRADE 25-06 ADL

ACCESSORIES N/STUDS SCOPE BASE L/SIGHTS

FROM:

Fred Suppy

SCOTT MAYS GUNSMITHING
1612 POST OAK ROAD
CORINTH TX 76205

SHIP TO:

SCOTT MAYS GUNSMITHING
1612 POST OAK ROAD
CORINTH TX 76205

CUST NO: 088708 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

Product Service

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

25.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			F1	F1
BOLT ASSY.		B3			F2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			G1	D3	E5	F5
METAL			G2			

MAIN FAULT

Left mfg 1973 upon receipt; unable to duplicate.

However, examination of rifle reveals that the action and trigger assembly are faulty and rusty. Rifle has fired several trigger adjustments & stop

PARTS

Repl. for maintenance

COMMENTS

Replace complete trigger assembly in clean action, at 1/2 normal replacement cost, as dictated by good & go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>CC</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 1/9