

Model 700
280 Cal.
Serial # A6817421

Arthur R. Shafer
5710 West "A" St.
West Linn, Or 97068

3/28/94

Remington Arms,

Mr. & Mrs. A.R. Shafer
5710 West "A" St.
West Linn, OR 97068

Two years ago this Model 700
280 caliber rifle discharged by
its self upon release of the safety.
The rifle was in the gun rack
in our pick up when this
accident occurred. The bullet went
through the side of the cab of
the pick up, then struck the
camper jack, then at that point
hit the hat on a mans head.
while ^{he was} walking across the parking
lot back to his own pick up.

I have owned this weapon
for about 15 years. This has never
happened before or since. We
took the rifle to a reputable
gun smith, neither he nor I
could make it discharge on its
own again.

Until we saw 60 min. on T.V.
we thought it was just fluk
accident. Please repair or replace
as soon as possible.

Thank !!

1-503-656-7439