

RECEIVING AND ESTIMATING REPORT

CUST NO: 049282 C.O.D.		COMMENTS: BOTTOM HALF OF SEE THRU MTS ONLY		ST-150	
DATE RECEIVED 9/13/91	DATE OPENED 09/17/91	DATE CODE OF 7-85	SERIAL NUMBER B6736270	MODEL AND GRADE 700 270	ORDER R 91-18337
CUSTOMER ORDER NO.			ADL		
CESSORIES			W/STUDS		

FROM:	SHIP TO:
SHAFER, EARL M SR 1 BOX 27A WALTON USA	SHAFER, EARL M SR 1 BOX 27A WALTON USA
WV 25286	WV 25286

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 10/2/91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	----------------------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: *"this gun has a fault in the firing mechanism"*

IN FAULT: *"no received, bolt release lever was broken and safety detent spring was broken. Trigger assembly is inoperable, as it is contaminated with a sticky residue - rear safety cam is stuck to assembly side plates and will not move. Rifle not properly maintained & apparently mis-used."*

RTS: *Send quotation for new trigger assembly,*

REPAIRMAN <i>XZ</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 7/90