

RECEIVING AND ESTIMATING REPORT

COMMENTS
ATTN JIM STEKL

CUSTOMER ORDER NO.

RECEIVED 14/90	DATE OPENED 12/19/90	DATE CODE EY 19-74	SERIAL NUMBER 6796517	MODEL AND GRADE 700 30-06 BDL	ORDER R 90-33235
-------------------	-------------------------	-----------------------	--------------------------	----------------------------------	---------------------

SERIES W/STUDS

A:

SHIFFER, DON
207 FAIRVEIW RD
CLARKS GREEN PA 18411

SHIP TO:

SHIFFER, DON
207 FAIRVEIW RD
CLARKS GREEN PA 18411

INT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
------------	--------------------	---	------------	-----------	------------

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

OWNER'S REQUEST

"This weapon discharged twice when safety was released"

AULT *No fault found - would not duplicate complaint - Trigger assembly operates properly. However, trigger assembly speed adjusted until factory (foreign solvent) properly. Trigger is 1/2 inch over min. spec at 2 3/4", over travel insufficient. Test - left O.K. at 1008"*

Offer to properly readjust present trigger assembly or, if it will better restore confidence in the rifle, we can install a new trigger assembly at 2 round cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

PPS 04483