not let accumulate in or on the trigger assembly. This condition could adversely affect the operation of the trigger assembly, especially during cold temperatures.

Ļ

Since we found your customer's firearm to be complete and function normally in every respect, we are prepared to have the rifle returned in its present condition. However, if your customer desires, we will install a new trigger assembly at no charge, as a gesture of good-will, if it will restore confidence in the rifle. We will await your customer's decision and reply.


Thank you for allowing us the opportunity to examine the rifle and report our findings.

Sincerely,

Product Service

DJS:tpp

Dear Mr. Sanita



Howldhauf HAROLD L. GUER

. .

SHOEMAKEK'S DUC. Remington Arms Company, Inc.